

DESERT VARNISH (PERMEON $^{\text{\tiny TM}}$) EVALUATION DABNEY STATE PARK (Region 1)

Construction Report

Experimental Features Project 94-02A

by

Eric W. Brooks, E.I.T Oregon Department of Transportation Research Group

for

Oregon Department of Transportation Research Group Salem OR 97301-5192

and

Federal Highway Administration Washington D.C. 20590

April 2000

REPRODUCED BY:
U.S. Department of Commerce
National Technical Information Service
Springfield, Virginia 22161

		I

Technical Report Documentation Page				
1. Report No.	2. Government Accession No.		3. Recipient's Catalog N	0.
OR-EF-00-11				
4. Title and Subtitle	<u> </u>		5. Report Date	
Desert Varnish (PERMEON [™] Dabney State Park	') EVALUATION		April 2000	
Construction Report			6. Performing Organizati	on Code
1				
7. Author(s)			8. Performing Organizati	on Report No.
Eric W. Brooks, E.I.T.				
9. Performing Organization Name and Address			10. Work Unit No. (TRA	AIS)
Oregon Department of Transport	ration			
Research Group	ation		11. Contract or Grant No	١.
200 Hawthorne SE, Suite B-240	1			
Salem, Oregon 97301-5192			SRF 306: 94-02A	Λ
12. Sponsoring Agency Name and Address	The state of the s		13. Type of Report and P	eriod Covered
Oregon Dept. of Transportation	Federal Highway	Administr	ation Construction Re	port
Research Group	and Washington, D.C		1999	•
200 Hawthorne SE, Suite B-240			14. Sponsoring Agency C	Tode .
Salem, Oregon 97301-5192			14. Sponsoring Agency	Louic
15.0				
15. Supplementary Notes				
16. Abstract				·
In 1998, ODOT mitigated a roo	ak fall hazard on the U	listorio C	olumbio Divor Highway	Loosa
rock was removed from the over			~ .	
covered with shotcrete to preve	ent erosion. The shoter	ete was t	hen coated with PERME	EON TM . a
form of artificial desert varnish				
varnish is a coloring agent inte				
in this area of high tourist traff	ic.			
m	1 61000 5	D1 1		.1
The project was completed in t				•
problems. It continues to darked cliff. This report documents the				naturai
_	e application and miti			
17. Key Words			ation Statement	
Desert Varnish, mitigation, shote	rete, PERMEON TM	Availab	le from the ODOT Researc	ch Group
19. Security Classification (of this report)	20. Security Classification (of t	his page)	21. No. of Pages	22. Price
Unclassified	Unclassified		24	

Technical Report Form DOT F 1700.7 (8-72)

Reproduction of completed page authorized

A	APPROXIMATE CONVERSIONS T	CONVERSIC	ONS TO SI UNITS	rs	AF	APPROXIMATE CONVERSIONS FROM SI UNITS	ONVERSIO	NS FROM SI UN	SLI
Symbol	When You Know	Multiply By	To Find	Symbol	Symbol	When You Know	Multiply By	To Find	Symbol
		LENGTH					LENGTH		
ii.	inches	25.4	millimeters	mm	mm	millimeters	0.039	inches	.i.
ft	feet	0.305	meters	ш	ш	meters	3.28	feet	ft
yd	yards	0.914	meters	ш	E	meters	1.09	yards	yd
mi	miles	1.61	kilometers	km	km	kilometers	0.621	miles	, <u>m</u>
		AREA					AREA		
in ²	square inches	645.2	millimeters squared	mm ²	mm^2	millimeters squared	0.0016	square inches	in ²
${ m ft}^2$	square feet	0.093	meters squared	m ²	m^2	meters squared	10.764	square feet	\mathfrak{ft}^2
yd²	square yards	0.836	meters squared	m²	ha	hectares	2.47	acres	ac
ac	acres	0.405	hectares	ha	km²	kilometers squared	0.386	square miles	mi ²
mi²	square miles	2.59	kilometers squared	km²			VOLUME		
		VOLUME			mL	milliliters	0.034	fluid ounces	fl oz
go lj	fluid onnces	29.57	milliliters	mL	Γ	liters	0.264	gallons	gal
gal	gallons	3.785	liters	Г	m³	meters cubed	35.315	cubic feet	ft.³
ft³	cubic feet	0.028	meters cubed	m³	m³	meters cubed	1.308	cubic yards	yd.³
yd^3	cubic yards	0.765	meters cubed	m³			MASS		
NOTE: Vol	NOTE: Volumes greater than 1000 L shall be shown in m^3 .	shall be shown in	1 m³.		bū	grams	0.035	onnces	ZO
		MASS		A.O	kg	kilograms	2.205	spunod	qı
Z0	onnces	28.35	grams	5ñ	Mg	megagrams	1.102	short tons (2000 lb)	L
lb	spunod	0.454	kilograms	kg		TEN	TEMPERATURE (exact)	(act)	
Т	short tons (2000 lb)	0.907	megagrams	Mg	သွ	Celsius temperature	1.8 + 32	Fahrenheit	÷.
	TEM	TEMPERATURE (exact)	<u>act)</u>				32 88.6 120	*F 212	
Ë	Fahrenheit temperature	5(F-32)/9	Celsius temperature	သ		- 20	20 40	- 8	
				•					

ACKNOWLEDGEMENTS

The author would like to thank the following Oregon Department of Transportation (ODOT) personnel for their contributions: Mark Beeson, Jim Hamburg, and Jeanette Kloos. Also, the author would like to thank Jill Livingston of Livingston, Inc. for the valuable information she provided at the jobsite.


PROTECTED UNDER INTERNATIONAL COPYRIGHT ALL RIGHTS RESERVED NATIONAL TECHNICAL INFORMATION SERVICE U.S. DEPARTMENT OF COMMERCE

DISCLAIMER

This document is disseminated under the sponsorship of the Oregon Department of Transportation and the United States Department of Transportation in the interest of information exchange. The State of Oregon and the United States Government assume no liability of its contents or use thereof.

The contents of this report reflect the views of the author, who is responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official policies of the Oregon Department of Transportation or the United States Department of Transportation.

The State of Oregon and the United States Government do not endorse products of manufacturers. Trademarks or manufacturers' names appear herein only because they are considered essential to the object of this document. This report does not constitute a standard, specification, or regulation.



DESERT VARNISH (PERMEON[™]) EVALUATION: DABNEY STATE PARK

TABLE OF CONTENTS

1.0 INTRODUCTION.......

1.1	STUDY OBJECTIVE AND METHODOLOGY	1
2.0 P	PROJECT DESCRIPTION	3
2.1	PROJECT LOCATION AND ENVIRONMENT	3
	CONSTRUCTION	
3.1 3.2 3.3		6
4.0 E	EVALUATIONS	9
4.1	CONCLUSIONS AND RECOMMENDATIONS	9
APPE:	NDIX A: Cross Section of Project Area NDIX B: Material Safety Data Sheet for PERMEON TM	
	LIST OF FIGURES/PHOTOS	
Figure 2	2.1: Project Vicinity Map	3
Figure 3	3.1: Spraying Equipment to Apply Desert Varnish	5
	3.2: Dark Streaks on Sandstone caused by Irrigation Water from Above	
Figure 4	4.2: Shotcrete West of Sandy River Bridge after Application of Desert Varnish	10
Figure 4	4.3: Shotcrete East of Sandy River Bridge before Application of Desert Varnish	11
Figure 4	4.4: Shotcrete East of Sandy River Bridge after Application of Desert Varnish	11

1.0 INTRODUCTION

Desert varnish is the name given to the brown to black coating that forms on stable rock surfaces in certain arid regions of the world. Natural desert varnish can be found in the Sahara Desert, the outback of Australia and the cold dry desert of Antarctica. It also appears in arid high-altitude mountains in Germany as well as on mountains in Colorado and Montana. No one has observed the natural formation of desert varnish, as it is an extremely slow geological process that may take up to 200,000 years to form.

In order to restore the natural appearance of rocky cliffs after construction, an artificial form of desert varnish was synthesized. Initially, the laboratory-created desert varnish was applied to projects in mountainous areas in Arizona, to comply with visual impact laws. This artificial desert varnish was used because reseeding and other reclamation efforts were not feasible. Concrete support structures have also been colored with desert varnish to blend in with the surroundings. The varnish has been used successfully on retaining walls, dams, irrigation ditches, and cliffs stabilized with shotcrete.

In 1995, the Oregon Department of Transportation (ODOT) used PERMEON[™], an artificial desert varnish, on a slope stabilization project on US 101 near Port Orford. The slope was shaped and reinforced with rock bolts and the bottom portion was covered with shotcrete. Because this scenic area attracts tourists from all over the world, desert varnish was applied to the shotcrete to help the project blend with the surroundings. After 5 years the varnish is still working well. It has given the gray shotcrete a marbled-brown appearance similar to other coastline cliffs in the area, and continues to blend even as the shotcrete and varnish age (Hofmann 1995, Brooks 1998).

A rock fall mitigation project on the Crown Point Highway was completed in 1998. After the loose rocks were removed manually, the base of the cliff was covered with shotcrete. Because the project is in the Columbia River Gorge National Scenic Area and is visited by many tourists, the shotcrete was colored with artificial desert varnish to reduce the visual impacts of the construction.

This report covers the application and initial evaluation of an artificial desert varnish (PERMEON[™]) to the Crown Point Highway project. Throughout this report, the PERMEON may be referred to as desert varnish.

1.1 STUDY OBJECTIVE AND METHODOLOGY

The objective of this project is to evaluate the effectiveness of PERMEON $^{\text{\tiny TM}}$ in producing a weathered, natural appearance when applied to shotcrete.

Photos were taken by the principal investigator at one week, one month and six months after application. Additional photos will be taken at one year and two years. Photos will also be taken

if the wall sustains any damage during this period that requires repairs. Landscape architects from ODOT and the US Forest Service will be asked to review and evaluate the photos after one year and two years.

2.0 PROJECT DESCRIPTION

2.1 PROJECT LOCATION AND ENVIRONMENT

The desert varnish was applied to the shotcrete used on the base of the cliff near Dabney State Park. This park is located east of Portland, Oregon along the Sandy River on the Crown Point Highway at milepost 4.1 (see Figure 2.1). The roadway has been designated as a National Scenic Route and is used by many tourists.




Figure 2.1: Project Vicinity Map

A cross section of the cliff is included in Appendix A. Located in the north Willamette Valley, the annual rainfall is about 1143 mm (45 in). The winters are mild with only a few freeze-thaw cycles. The mean January temperature is 4 °C (39 °F), while the mean July temperature is 21 °C (69 °F).

3.0 CONSTRUCTION

PERMEONTM is an artificial desert varnish. The material can be diluted to match the surrounding rocks, and applied in different concentrations to resemble natural earth coloring. Manufacturer's instructions state that PERMEONTM should not be applied in rainy or windy conditions, and a weather forecast of at least two hours of no rain after application is recommended.

3.1 APPLICATION

Application of the desert varnish was delayed for several months because of wet weather (desert varnish must be applied to a dry surface). On July 14, 1999, final preparations were made, as there was no rain forecast for the next 24 hours, with only a 20% chance of light showers late on the night of July 15. The contractor prepared the surface by pressure washing the shotcrete, which had been applied the prior year and had some natural buildup of dirt and minerals.

The next morning, the desert varnish application went smoothly, with about 76.25 m (250 ft) completed by 10:00 a.m. The PERMEON[™] (desert varnish) had been mixed with water in a 5:1 solution, 76 L (20 gal) of PERMEON[™] to 100 gallons of water. The mix was carried in the back of a pickup truck in a 950 L (250gal) tank. A compressor was used to pressurize the spray to about 1380 kPa (200 psi). The sub-contractor, Livingston, Inc., used a 200-foot hose and an agricultural-type hand-held nozzle to spray the shotcrete-coated cliff. The equipment is shown in Figure 3.1.




Figure 3.1: Spraying Equipment to Apply Desert Varnish

The weather was sunny and warm. Traffic was routed one-way in the eastbound lane. The base of the newly cut rock slope was then about 7.6 m (25 ft) from the passing cars. Because of the low height to be sprayed and low wind conditions, overspray hitting passing cars was not a problem. Traffic was light and the delay due to the one-way travel was very short.

Jill Livingston, who was doing the desert varnish application, has extensive experience with the product. She said that the color can range from almost black to a light tan, depending on the concentration of PERMEONTM and the number of coats applied. The solution was sprayed on until saturation, when it started to run off the shotcrete. At the saturated value, the artificial desert varnish was intended to match the light brown rocks above.

The application went very well, with no complaints about over-spray. Application was completed with materials on hand and no breakdowns occurred.

3.2 MATERIAL DESCRIPTION

When first applied, the PERMEONTM mixture does not have a tint, and the shotcrete returns to its original light gray color as it dries. The coloration process is activated by exposure to ultraviolet light from sunshine. The formulation was selected by spraying test bricks and leaving them for the required exposure time. Because some of the cliff above the shotcrete was darker, additional coats could be required, but because it takes at least a week for the PERMEONTM color to develop, another trip would be required to achieve a darker coloration.

The material safety data sheet for the PERMEON[™] indicates that it contains salts of manganese and iron with trace elements chlorine, copper, zinc and phosphoric oxides (see Appendix B). Since PERMEON[™] can stain clothing and other materials, traffic control or coverings may be needed to prevent over-spray damage. At the concentrations used, Jill Livingston said the mixture would not kill roadside vegetation or affect fish in nearby streams with running water, but she cautioned that still water, such as small fishponds, should be covered when PERMEON[™] is applied nearby.

3.3 POSSIBLE PROBLEMS

Two possible problems were noted: water running over the cliff in a few areas from a local land owners' irrigation effort on the hill above the site (see Figure 3.2), and mineral stains from an unknown source appearing on some of the rocks just above the shotcrete. These two areas should be closely monitored.

Also noted were some cracks in the shotcrete running vertically up the cliff. Some of these cracks extended from weep-hole to weep-hole. These could be potential break-points for the shotcrete. Near the top of the desert varnish, there are areas of overhang which could also be breaking points.




Figure 3.2: Dark Streaks on Shotcrete caused by Irrigation Water from Above

4.0 EVALUATIONS AND CONCLUSIONS

Jeanette Kloos, ODOT's Historic Columbia River Highway Coordinator, monitored the project as principal investigator. Photographs and inspections were scheduled to be taken at one week, one month, six months, one year and a final inspection after two years. Photographs will be compared and evaluated for the aesthetic value of the desert varnish application. A final report will be written soon after the final inspection is completed.

After two weeks, half of the shotcrete with the desert varnish was starting to blend well with the surrounding cliff. The section west of the bridge is well matched, as can be seen by comparing Figures 4.1 and 4.2, which show the condition before and two weeks after construction. East of the bridge, the section is still lighter than the cliff, as shown in Figures 4.3 and 4.4, which also show the before and two weeks after construction condition. This section will be watched closely as it should darken with age.

4.1 CONCLUSIONS AND RECOMMENDATIONS

The desert varnish application went smoothly, with traffic easily controlled, all materials on hand, and no breakdowns. Weather conditions were ideal for this application and no complaints were filed about over-spray. Waiting for good weather conditions is a must with this product, in order for it to cure properly without streaking.

An experienced company completed the application. Because the correct application rate is an art learned by experience, it is recommended that future jobs be done only by experienced people.

Because of the continued change in the desert varnish coloration, it is recommended that the desert varnish application be monitored for two years.




Figure 4.1: Shotcrete West of Sandy River Bridge before Application of Desert Varnish



Figure 4.2: Shotcrete West of Sandy River Bridge after Application of Desert Varnish




Figure 4.3: Shotcrete East of Sandy River Bridge before Application of Desert Varnish



Figure 4.4: Shotcrete East of Sandy River Bridge after Application of Desert Varnish

5.0 REFERENCES


Brooks, Eric. *Desert Varnish: Rocky Point Viaduct. Final Report.* Oregon Department of Transportation, Research Unit. November 1998.

Hofmann, Kaaren. *Desert Varnish: Rocky Point Viaduct. Construction Report.* Oregon Department of Transportation, Research Unit. January 1996.

APPENDICES

APPENDIX A: PROJECT CROSS SECTION APPENDIX B: MATERIAL SAFETY DATA SHEET

APPENDIX A



APPENDIX B

MATERIAL SAFETY DATA SHEET

SECTION I ********** PRODUCT IDENTIFICATION **********

TRADE NAME (AS LABELED) PERMEON

COMMON SYNONYMS:

ARTIFICIAL DESERT VARNISH

CHEMICAL FAMILY:

SOLUBLE CHEMICAL SALTS IN WATER

INGREDIENTS:

IRON AND MANGANESE SALTS WITH TRACE ELEMENTS INCLUDING C1, PO. CU, ZN AND

INSOLUBLE MATTER.

MANUFACTURER'S NAME:

ADDRESS: PHONE:

ADVANCED CONCRETE TECHNOLOGIES

11622 NEWPORT AVENUE SANTA ANA CA 92705

714 731-0906

DATE PREPARED SEPTEMBER 1, 1992

******* PRECAUTIONARY LABELING *************

CERCLA RATINGS (SCALE 0-3) HEALTH 2 FIRE 0

REACTIVITY O FIRE 0

NPPA RATINGS (SCALE 0-4)

REALTH 2 FLAMMABILITY 0 REACTIVITY 0

BAKER SAF-T DATA (SCALE 0-4)
HEALTH 1 FLAMMABILITY O REACTIVITY O CONTACT O

PRECAUTIONARY LABEL STATEMENTS

AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION WASH AFTER HANDLING. SAFETY GLASSES RECOMMENDED.

SECTION II ******** HAZARDOUS COMPONENTS ***********

NOT APPLICABLE - STABLE

SECTION III ******* PHYSICAL DATA **************

WATER SOLUTION - CLEAR TO BROWN COLOR

SECTION IV ******** FIRE AND EXPLOSION HAZARD DATA *********

NOT APPLICABLE

PAGE 1 of 2

MATERIAL SAFETY DATA SHEET

PERMEON	PAGE 2 OF 2
SECTION V *********** PHYSIOLOGICAL REFECTS ****	*********
HEALTH INFORMATION AND FIRST AID PROCE EYE EPPECTS: PRODUCT IN CONCENTRATED I IRRITATION. IF IRRITATION PERSISTS, S ATTENTION.	FORM MAY CAUSE
SECTION VI *********** REACTIVITY *********	t**********
STABLLITY: STABLE DECOMPOSITION PRODUCTS: OXIDES OF IRO	ON AND MANGANESE
SECTION VII ******* SPILL AND DISPOSAL PROCEDURES *	*****
Wash with water. May stain concrete. Accordance with local environmental re	DISPOSE IN EGULATIONS.
SECTION VIII *********************************	****
VENTILATION: USE WITH ADEQUATE VENTIL RESPIRATORY PROTECTION: NONE REQUIRED VENTILATION.	
EYE/SKIN PROTECTION: SAFETY GLASSES P	ecommended.
section ix ************** Storage and Handling **	******
STORE IN COOL, DRY PLACE IN TIGHTLY CLO OTHER PRECAUTIONS: USE GOOD PERSONAL H INHALATION OF HISTS AND PROLONGED SKIN	YGIENE. AVOID
SECTION X ************ TRANSPORTATION DATA ****	******
(TM) AND (R) DESIGNATED TRADEMARKS - P	ERMEON
Carry Andrew Carry	

THE INFORMATION PUBLISHED IN THIS MATERIAL SAFETY DATA SHEET HAS BEEN COMPILED FROM OUR EXPERIENCE AND DATA PRESENTED IN VARIOUS TECHNICAL PUBLICATIONS INCLUDING MATERIAL SAFETY DATA SHEETS PROVIDED BY J.T. BAKER CHEMICAL COMPANY, FISHER SCIENTIFIC CHEMICAL DIVISION AND JOHNSON MATTHEY CHEMICALS.